



Windaus
Umwelttechnik

Photometerbox

Betriebsanleitungen
für Ökologie- und Umweltschutzmeßgeräte



Windaus



25-03-2010 18:02:21

Chromium +

Cr⁶⁺

Measure blind

Windaus
Labortechnik

Data Line

OFF

ESC

ENTER

MENU

WinLab® PHOTOMETER



HELP



↑



0,0



MEM



↓



mg/l



25-03-2010 17:29:55

Copper WinLab
Cu²⁺

< **0.09** mg/l

Winlab 800320203
Measure Ready

Windaus
Labortechnik

Data Line

OFF

ESC

ENTER

MENU

WinLab® PHOTOMETER



HELP



↑



0,0



MEM



↓



mg/l



Setup MENU BAT 60%

[X]	Absorbance	380
[X]	Absorbance	430
[X]	Absorbance	470
[X]	Absorbance	500
[X]	Absorbance	520
<input checked="" type="checkbox"/>	Absorbance	560



History View

Logger View

Logger Erase

Help

Setup

25-03-2006

17:29:55

COPPER

WinLab

Cu²⁺

< 0.09

mg/l

Winlab 800320203

Measure Ready

Windaus
— Labortechnik —

Data Line



WinLab Data Line

ESC ENTER MENU
WinLab[®] PHOTOMETER
HELP 0.0
MEM mg/l





